

# PEER Chain Sprockets Shopping List


Below is a list of the 1,200 sprockets we are adding to our regular inventory! Please check the sprockets you use to help us get a quote together to discuss with you! All sprockets listed below come Black Oxide Coated.

PEER Chain sprockets and roller chain —  
PEER Perfectly Pairs!

## A-Hub Sprockets



*Sparky Sprocket*



### #35 A-Hub Sprockets

- ☐ PC35A15H x 1/2" PLN BORE-HT
- ☐ PC35A16H x 1/2" PLN BORE-HT
- ☐ PC35A17H x 1/2" PLN BORE-HT
- ☐ PC35A18H x 1/2" PLN BORE-HT
- ☐ PC35A19H x 1/2" PLN BORE-HT
- ☐ PC35A20H x 1/2" PLN BORE-HT
- ☐ PC35A21H x 1/2" PLN BORE-HT
- ☐ PC35A22H x 1/2" PLN BORE-HT
- ☐ PC35A23H x 1/2" PLN BORE-HT
- ☐ PC35A24H x 1/2" PLN BORE-HT
- ☐ PC35A25H x 1/2" PLN BORE-HT
- ☐ PC35A26H x 1/2" PLN BORE-HT
- ☐ PC35A27H x 1/2" PLN BORE-HT
- ☐ PC35A28H x 1/2" PLN BORE-HT
- ☐ PC35A30H x 1/2" PLN BORE-HT
- ☐ PC35A32H x 5/8" PLN BORE-HT
- ☐ PC35A35H x 5/8" PLN BORE-HT

### #40 A-Hub Sprockets

- ☐ PC40A12H x 1/2" PLN BORE-HT
- ☐ PC40A13H x 1/2" PLN BORE-HT
- ☐ PC40A14H x 1/2" PLN BORE-HT
- ☐ PC40A15H x 5/8" PLN BORE-HT
- ☐ PC40A16H x 5/8" PLN BORE-HT
- ☐ PC40A17H x 5/8" PLN BORE-HT
- ☐ PC40A18H x 5/8" PLN BORE-HT
- ☐ PC40A19H x 5/8" PLN BORE-HT
- ☐ PC40A20H x 5/8" PLN BORE-HT
- ☐ PC40A21H x 5/8" PLN BORE-HT
- ☐ PC40A22H x 5/8" PLN BORE-HT
- ☐ PC40A23H x 5/8" PLN BORE-HT
- ☐ PC40A24H x 5/8" PLN BORE-HT
- ☐ PC40A25H x 5/8" PLN BORE-HT
- ☐ PC40A26H x 5/8" PLN BORE-HT
- ☐ PC40A27H x 5/8" PLN BORE-HT
- ☐ PC40A28H x 5/8" PLN BORE-HT
- ☐ PC40A29H x 19/32" PLN BORE-HT
- ☐ PC40A30H x 19/32" PLN BORE-HT

- ☐ PC40A31H x 19/32" PLN BORE-HT
- ☐ PC40A32H x 19/32" PLN BORE-HT
- ☐ PC40A33H x 19/32" PLN BORE-HT
- ☐ PC40A34H x 19/32" PLN BORE-HT
- ☐ PC40A35H x 19/32" PLN BORE-HT
- ☐ PC40A36H x 19/32" PLN BORE-HT
- ☐ PC40A37H x 19/32" PLN BORE-HT
- ☐ PC40A38H x 19/32" PLN BORE-HT
- ☐ PC40A39H x 19/32" PLN BORE-HT
- ☐ PC40A40H x 23/32" PLN BORE-HT

### #50 A-Hub Sprockets

- ☐ PC50A09H x 5/8" PLN BORE-HT
- ☐ PC50A10H x 5/8" PLN BORE-HT
- ☐ PC50A11H x 5/8" PLN BORE-HT
- ☐ PC50A12H x 5/8" PLN BORE-HT
- ☐ PC50A13H x 5/8" PLN BORE-HT
- ☐ PC50A14H x 5/8" PLN BORE-HT
- ☐ PC50A15H x 5/8" PLN BORE-HT
- ☐ PC50A16H x 5/8" PLN BORE-HT
- ☐ PC50A17H x 5/8" PLN BORE-HT
- ☐ PC50A18H x 5/8" PLN BORE-HT
- ☐ PC50A19H x 5/8" PLN BORE-HT
- ☐ PC50A20H x 3/4" PLN BORE-HT
- ☐ PC50A21H x 3/4" PLN BORE-HT
- ☐ PC50A22H x 3/4" PLN BORE-HT
- ☐ PC50A23H x 3/4" PLN BORE-HT
- ☐ PC50A24H x 23/32" PLN BORE-HT
- ☐ PC50A25H x 23/32" PLN BORE-HT
- ☐ PC50A26H x 23/32" PLN BORE-HT
- ☐ PC50A27H x 23/32" PLN BORE-HT
- ☐ PC50A28H x 23/32" PLN BORE-HT
- ☐ PC50A29H x 23/32" PLN BORE-HT
- ☐ PC50A30H x 23/32" PLN BORE-HT
- ☐ PC50A31H x 23/32" PLN BORE-HT
- ☐ PC50A32H x 23/32" PLN BORE-HT
- ☐ PC50A33H x 23/32" PLN BORE-HT
- ☐ PC50A34H x 23/32" PLN BORE-HT



*Uncle Line*

- ☐ PC50A35H x 23/32" PLN BORE-HT
- ☐ PC50A36H x 23/32" PLN BORE-HT
- ☐ PC50A37H x 23/32" PLN BORE-HT
- ☐ PC50A38H x 23/32" PLN BORE-HT
- ☐ PC50A39H x 23/32" PLN BORE-HT
- ☐ PC50A40H x 23/32" PLN BORE-HT

### #60 A-Hub Sprockets

- ☐ PC60A09H x 3/4" PLN BORE-HT
- ☐ PC60A10H x 3/4" PLN BORE-HT
- ☐ PC60A11H x 3/4" PLN BORE-HT
- ☐ PC60A12H x 3/4" PLN BORE-HT
- ☐ PC60A13H x 3/4" PLN BORE-HT
- ☐ PC60A14H x 3/4" PLN BORE-HT
- ☐ PC60A15H x 3/4" PLN BORE-HT
- ☐ PC60A16H x 3/4" PLN BORE-HT
- ☐ PC60A17H x 3/4" PLN BORE-HT
- ☐ PC60A18H x 3/4" PLN BORE-HT
- ☐ PC60A19H x 3/4" PLN BORE-HT
- ☐ PC60A20H x 3/4" PLN BORE-HT
- ☐ PC60A21H x 3/4" PLN BORE-HT
- ☐ PC60A22H x 3/4" PLN BORE-HT
- ☐ PC60A23H x 3/4" PLN BORE-HT
- ☐ PC60A24H x 23/32" PLN BORE-HT
- ☐ PC60A25H x 23/32" PLN BORE-HT
- ☐ PC60A26H x 23/32" PLN BORE-HT
- ☐ PC60A27H x 23/32" PLN BORE-HT
- ☐ PC60A28H x 23/32" PLN BORE-HT
- ☐ PC60A29H x 23/32" PLN BORE-HT
- ☐ PC60A30H x 23/32" PLN BORE-HT
- ☐ PC60A31 x 23/32" PLN BORE
- ☐ PC60A32 x 23/32" PLN BORE

## PEER Chain Sprockets

- ☐ PC60A33 x 15/16" PLN BORE
- ☐ PC60A34 x 15/16" PLN BORE
- ☐ PC60A35 x 15/16" PLN BORE
- ☐ PC60A36 x 15/16" PLN BORE
- ☐ PC60A37 x 15/16" PLN BORE
- ☐ PC60A38 x 15/16" PLN BORE
- ☐ PC60A39 x 15/16" PLN BORE
- ☐ PC60A40 x 15/16" PLN BORE

### #80 A-Hub Sprockets

- ☐ PC80A09H x 15/16" PLN BORE-HT
- ☐ PC80A10H x 15/16" PLN BORE-HT
- ☐ PC80A11H x 15/16" PLN BORE-HT
- ☐ PC80A12H x 15/16" PLN BORE-HT
- ☐ PC80A13H x 15/16" PLN BORE-HT
- ☐ PC80A14H x 15/16" PLN BORE-HT
- ☐ PC80A15H x 15/16" PLN BORE-HT
- ☐ PC80A16H x 15/16" PLN BORE-HT
- ☐ PC80A17H x 15/16" PLN BORE-HT
- ☐ PC80A18H x 15/16" PLN BORE-HT
- ☐ PC80A19H x 15/16" PLN BORE-HT
- ☐ PC80A20H x 15/16" PLN BORE-HT
- ☐ PC80A21H x 15/16" PLN BORE-HT
- ☐ PC80A22H x 15/16" PLN BORE-HT
- ☐ PC80A23 x 15/16" PLN BORE
- ☐ PC80A24 x 15/16" PLN BORE
- ☐ PC80A25 x 15/16" PLN BORE
- ☐ PC80A26 x 1-3/16" PLN BORE
- ☐ PC80A27 x 1-3/16" PLN BORE
- ☐ PC80A28 x 1-3/16" PLN BORE
- ☐ PC80A29 x 1-3/16" PLN BORE
- ☐ PC80A30 x 1-3/16" PLN BORE
- ☐ PC80A31 x 1-3/16" PLN BORE
- ☐ PC80A32 x 1-3/16" PLN BORE
- ☐ PC80A33 x 1-3/16" PLN BORE
- ☐ PC80A34 x 1-3/16" PLN BORE
- ☐ PC80A35 x 1-3/16" PLN BORE
- ☐ PC80A36 x 1-3/16" PLN BORE
- ☐ PC80A37 x 1-3/16" PLN BORE
- ☐ PC80A38 x 1-3/16" PLN BORE
- ☐ PC80A39 x 1-3/16" PLN BORE
- ☐ PC80A40 x 1-3/16" PLN BORE

## Plain Bore B-Hub Sprockets



### #35 B-Hub Plain Bore Sprockets

- ☐ PC35B10H x 3/8" PLN BORE-HT
- ☐ PC35B11H x 3/8" PLN BORE-HT
- ☐ PC35B12H x 1/2" PLN BORE-HT
- ☐ PC35B13H x 1/2" PLN BORE-HT

- ☐ PC35B14H x 1/2" PLN BORE-HT
- ☐ PC35B15H x 1/2" PLN BORE-HT
- ☐ PC35B16H x 1/2" PLN BORE-HT
- ☐ PC35B17H x 1/2" PLN BORE-HT
- ☐ PC35B18H x 1/2" PLN BORE-HT
- ☐ PC35B19H x 1/2" PLN BORE-HT
- ☐ PC35B20H x 1/2" PLN BORE-HT
- ☐ PC35B21H x 1/2" PLN BORE-HT
- ☐ PC35B22H x 1/2" PLN BORE-HT
- ☐ PC35B23H x 1/2" PLN BORE-HT
- ☐ PC35B24H x 1/2" PLN BORE-HT
- ☐ PC35B25H x 1/2" PLN BORE-HT
- ☐ PC35B26H x 1/2" PLN BORE-HT
- ☐ PC35B27H x 1/2" PLN BORE-HT
- ☐ PC35B28H x 1/2" PLN BORE-HT
- ☐ PC35B30H x 1/2" PLN BORE-HT
- ☐ PC35B32H x 1/2" PLN BORE-HT
- ☐ PC35B35H x 5/8" PLN BORE-HT
- ☐ PC35B36H x 5/8" PLN BORE-HT
- ☐ PC35B40H x 5/8" PLN BORE-HT

### #40 B-Hub Plain Bore Sprockets

- ☐ PC40B09H x 1/2" PLN BORE-HT
- ☐ PC40B10H x 1/2" PLN BORE-HT
- ☐ PC40B11H x 1/2" PLN BORE-HT
- ☐ PC40B12H x 1/2" PLN BORE-HT
- ☐ PC40B13H x 1/2" PLN BORE-HT
- ☐ PC40B14H x 1/2" PLN BORE-HT
- ☐ PC40B15H x 1/2" PLN BORE-HT
- ☐ PC40B16H x 5/8" PLN BORE-HT
- ☐ PC40B17H x 5/8" PLN BORE-HT
- ☐ PC40B18H x 5/8" PLN BORE-HT
- ☐ PC40B19H x 5/8" PLN BORE-HT
- ☐ PC40B20H x 5/8" PLN BORE-HT
- ☐ PC40B21H x 5/8" PLN BORE-HT
- ☐ PC40B22H x 5/8" PLN BORE-HT
- ☐ PC40B23H x 5/8" PLN BORE-HT
- ☐ PC40B24H x 5/8" PLN BORE-HT
- ☐ PC40B25H x 5/8" PLN BORE-HT
- ☐ PC40B26H x 5/8" PLN BORE-HT
- ☐ PC40B27H x 5/8" PLN BORE-HT
- ☐ PC40B28H x 5/8" PLN BORE-HT
- ☐ PC40B29H x 5/8" PLN BORE-HT
- ☐ PC40B30H x 5/8" PLN BORE-HT
- ☐ PC40B31H x 5/8" PLN BORE-HT
- ☐ PC40B32H x 5/8" PLN BORE-HT
- ☐ PC40B33H x 5/8" PLN BORE-HT
- ☐ PC40B34H x 5/8" PLN BORE-HT
- ☐ PC40B35H x 5/8" PLN BORE-HT
- ☐ PC40B36H x 5/8" PLN BORE-HT
- ☐ PC40B37H x 5/8" PLN BORE-HT
- ☐ PC40B38H x 5/8" PLN BORE-HT
- ☐ PC40B39H x 5/8" PLN BORE-HT
- ☐ PC40B40H x 3/4" PLN BORE-HT

### #50 B-Hub Plain Bore Sprockets

- ☐ PC50B09H x 5/8" PLN BORE-HT
- ☐ PC50B10H x 5/8" PLN BORE-HT
- ☐ PC50B11H x 5/8" PLN BORE-HT
- ☐ PC50B12H x 5/8" PLN BORE-HT
- ☐ PC50B13H x 5/8" PLN BORE-HT
- ☐ PC50B14H x 5/8" PLN BORE-HT
- ☐ PC50B15H x 5/8" PLN BORE-HT
- ☐ PC50B16H x 5/8" PLN BORE-HT
- ☐ PC50B17H x 5/8" PLN BORE-HT
- ☐ PC50B18H x 5/8" PLN BORE-HT
- ☐ PC50B19H x 5/8" PLN BORE-HT
- ☐ PC50B20H x 3/4" PLN BORE-HT
- ☐ PC50B21H x 3/4" PLN BORE-HT
- ☐ PC50B22H x 3/4" PLN BORE-HT
- ☐ PC50B23H x 3/4" PLN BORE-HT
- ☐ PC50B24H x 3/4" PLN BORE-HT
- ☐ PC50B25H x 3/4" PLN BORE-HT
- ☐ PC50B26H x 3/4" PLN BORE-HT
- ☐ PC50B27H x 3/4" PLN BORE-HT
- ☐ PC50B28H x 3/4" PLN BORE-HT
- ☐ PC50B29H x 3/4" PLN BORE-HT
- ☐ PC50B30H x 3/4" PLN BORE-HT
- ☐ PC50B31H x 3/4" PLN BORE-HT
- ☐ PC50B32H x 3/4" PLN BORE-HT
- ☐ PC50B33H x 3/4" PLN BORE-HT
- ☐ PC50B34H x 3/4" PLN BORE-HT

### #60 B-Hub Plain Bore Sprockets

- ☐ PC60B09H x 3/4" PLN BORE-HT
- ☐ PC60B10H x 3/4" PLN BORE-HT
- ☐ PC60B11H x 3/4" PLN BORE-HT
- ☐ PC60B12H x 3/4" PLN BORE-HT
- ☐ PC60B13H x 3/4" PLN BORE-HT
- ☐ PC60B14H x 3/4" PLN BORE-HT
- ☐ PC60B15H x 3/4" PLN BORE-HT
- ☐ PC60B16H x 3/4" PLN BORE-HT
- ☐ PC60B17H x 3/4" PLN BORE-HT
- ☐ PC60B18H x 3/4" PLN BORE-HT
- ☐ PC60B19H x 3/4" PLN BORE-HT
- ☐ PC60B20H x 3/4" PLN BORE-HT
- ☐ PC60B21H x 3/4" PLN BORE-HT
- ☐ PC60B22H x 3/4" PLN BORE-HT
- ☐ PC60B23H x 3/4" PLN BORE-HT
- ☐ PC60B24H x 3/4" PLN BORE-HT
- ☐ PC60B25H x 3/4" PLN BORE-HT
- ☐ PC60B26H x 3/4" PLN BORE-HT
- ☐ PC60B27H x 3/4" PLN BORE-HT
- ☐ PC60B28H x 3/4" PLN BORE-HT
- ☐ PC60B29H x 3/4" PLN BORE-HT
- ☐ PC60B30H x 3/4" PLN BORE-HT
- ☐ PC60B31 x 3/4" PLN BORE
- ☐ PC60B32 x 3/4" PLN BORE

### #80 B-Hub Plain Bore Sprockets

- ☐ PC80B09H x 1" PLN BORE-HT
- ☐ PC80B10H x 1" PLN BORE-HT
- ☐ PC80B11H x 1" PLN BORE-HT
- ☐ PC80B12H x 1" PLN BORE-HT
- ☐ PC80B13H x 1" PLN BORE-HT
- ☐ PC80B14H x 1" PLN BORE-HT
- ☐ PC80B15H x 1" PLN BORE-HT
- ☐ PC80B16H x 1" PLN BORE-HT
- ☐ PC80B17H x 1" PLN BORE-HT
- ☐ PC80B18H x 1" PLN BORE-HT
- ☐ PC80B19H x 1" PLN BORE-HT
- ☐ PC80B20H x 1" PLN BORE-HT
- ☐ PC80B21H x 1" PLN BORE-HT
- ☐ PC80B22H x 1" PLN BORE-HT
- ☐ PC80B23 x 1" PLN BORE
- ☐ PC80B24 x 1" PLN BORE
- ☐ PC80B25 x 1" PLN BORE
- ☐ PC80B26 x 1-1/4" PLN BORE
- ☐ PC80B27 x 1-1/4" PLN BORE
- ☐ PC80B28 x 1-1/4" PLN BORE
- ☐ PC80B29 x 1-3/16" PLN BORE
- ☐ PC80B30 x 1-3/16" PLN BORE
- ☐ PC80B31 x 1-3/16" PLN BORE
- ☐ PC80B32 x 1-3/16" PLN BORE
- ☐ PC80B33 x 1-3/16" PLN BORE
- ☐ PC80B34 x 1-3/16" PLN BORE
- ☐ PC80B35 x 1-3/16" PLN BORE
- ☐ PC80B36 x 1-3/16" PLN BORE

## Finished Bore B-Hub Sprockets



### #35 B-Hub Finished Bore Sprockets

- ☐ PC35B09HF x 3/8"FB,KW2SS,HT
- ☐ PC35B10HF x 3/8"FB,KW2SS,HT
- ☐ PC35B10HF x 1/2"FB,KW2SS,HT
- ☐ PC35B11HF x 1/2"FB,KW2SS,HT
- ☐ PC35B12HF x 1/2"FB,KW2SS,HT
- ☐ PC35B13HF x 1/2"FB,KW2SS,HT
- ☐ PC35B14HF x 1/2"FB,KW2SS,HT
- ☐ PC35B15HF x 1/2"FB,KW2SS,HT
- ☐ PC35B16HF x 1/2"FB,KW2SS,HT
- ☐ PC35B17HF x 1/2"FB,KW2SS,HT
- ☐ PC35B18HF x 1/2"FB,KW2SS,HT
- ☐ PC35B19HF x 1/2"FB,KW2SS,HT
- ☐ PC35B20HF x 1/2"FB,KW2SS,HT
- ☐ PC35B21HF x 1/2"FB,KW2SS,HT
- ☐ PC35B22HF x 1/2"FB,KW2SS,HT
- ☐ PC35B23HF x 1/2"FB,KW2SS,HT
- ☐ PC35B24HF x 1/2"FB,KW2SS,HT
- ☐ PC35B25HF x 1/2"FB,KW2SS,HT
- ☐ PC35B09HF x 5/8"FB,KW2SS,HT

- ☐ PC35B10HF x 5/8"FB,KW2SS,HT
- ☐ PC35B11HF x 5/8"FB,KW2SS,HT
- ☐ PC35B12HF x 5/8"FB,KW2SS,HT
- ☐ PC35B13HF x 5/8"FB,KW2SS,HT
- ☐ PC35B14HF x 5/8"FB,KW2SS,HT
- ☐ PC35B15HF x 5/8"FB,KW2SS,HT
- ☐ PC35B16HF x 5/8"FB,KW2SS,HT
- ☐ PC35B17HF x 5/8"FB,KW2SS,HT
- ☐ PC35B18HF x 5/8"FB,KW2SS,HT
- ☐ PC35B19HF x 5/8"FB,KW2SS,HT
- ☐ PC35B20HF x 5/8"FB,KW2SS,HT
- ☐ PC35B21HF x 5/8"FB,KW2SS,HT
- ☐ PC35B22HF x 5/8"FB,KW2SS,HT
- ☐ PC35B23HF x 5/8"FB,KW2SS,HT
- ☐ PC35B24HF x 5/8"FB,KW2SS,HT
- ☐ PC35B25HF x 5/8"FB,KW2SS,HT
- ☐ PC35B26HF x 5/8"FB,KW2SS,HT
- ☐ PC35B27HF x 5/8"FB,KW2SS,HT
- ☐ PC35B28HF x 5/8"FB,KW2SS,HT
- ☐ PC35B30HF x 5/8"FB,KW2SS,HT
- ☐ PC35B32HF x 5/8"FB,KW2SS,HT
- ☐ PC35B35HF x 5/8"FB,KW2SS,HT
- ☐ PC35B36HF x 5/8"FB,KW2SS,HT
- ☐ PC35B40HF x 5/8"FB,KW2SS,HT
- ☐ PC35B42HF x 5/8"FB,KW2SS,HT
- ☐ PC35B45HF x 5/8"FB,KW2SS,HT
- ☐ PC35B09HF x 1"FB,KW2SS,HT
- ☐ PC35B10HF x 1"FB,KW2SS,HT
- ☐ PC35B11HF x 1"FB,KW2SS,HT
- ☐ PC35B12HF x 1"FB,KW2SS,HT
- ☐ PC35B13HF x 1"FB,KW2SS,HT
- ☐ PC35B14HF x 1"FB,KW2SS,HT
- ☐ PC35B15HF x 1"FB,KW2SS,HT
- ☐ PC35B16HF x 1"FB,KW2SS,HT
- ☐ PC35B17HF x 1"FB,KW2SS,HT
- ☐ PC35B18HF x 1"FB,KW2SS,HT
- ☐ PC35B19HF x 1"FB,KW2SS,HT
- ☐ PC35B20HF x 1"FB,KW2SS,HT
- ☐ PC35B21HF x 1"FB,KW2SS,HT
- ☐ PC35B22HF x 1"FB,KW2SS,HT
- ☐ PC35B23HF x 1"FB,KW2SS,HT
- ☐ PC35B24HF x 1"FB,KW2SS,HT
- ☐ PC35B25HF x 1"FB,KW2SS,HT
- ☐ PC35B26HF x 1"FB,KW2SS,HT
- ☐ PC35B27HF x 1"FB,KW2SS,HT
- ☐ PC35B28HF x 1"FB,KW2SS,HT
- ☐ PC35B30HF x 1"FB,KW2SS,HT
- ☐ PC35B32HF x 1"FB,KW2SS,HT
- ☐ PC35B35HF x 1"FB,KW2SS,HT
- ☐ PC35B36HF x 1"FB,KW2SS,HT
- ☐ PC35B40HF x 1"FB,KW2SS,HT
- ☐ PC35B42HF x 1"FB,KW2SS,HT
- ☐ PC35B45HF x 1"FB,KW2SS,HT
- ☐ PC35B26HF x 1-1/8"FB,KW2SS,HT

### PEER Chain Sprockets

- ☐ PC35B27HF x 1-1/8"FB,KW2SS,HT
- ☐ PC35B28HF x 1-1/8"FB,KW2SS,HT
- ☐ PC35B30HF x 1-1/8"FB,KW2SS,HT
- ☐ PC35B32HF x 1-1/8"FB,KW2SS,HT
- ☐ PC35B35HF x 1-1/8"FB,KW2SS,HT
- ☐ PC35B36HF x 1-1/8"FB,KW2SS,HT
- ☐ PC35B40HF x 1-1/8"FB,KW2SS,HT
- ☐ PC35B42HF x 1-1/8"FB,KW2SS,HT
- ☐ PC35B45HF x 1-1/8"FB,KW2SS,HT
- ☐ PC35B26HF x 1-3/16"FB,KW2SS,HT
- ☐ PC35B27HF x 1-3/16"FB,KW2SS,HT
- ☐ PC35B28HF x 1-3/16"FB,KW2SS,HT
- ☐ PC35B30HF x 1-3/16"FB,KW2SS,HT
- ☐ PC35B32HF x 1-3/16"FB,KW2SS,HT
- ☐ PC35B35HF x 1-3/16"FB,KW2SS,HT
- ☐ PC35B36HF x 1-3/16"FB,KW2SS,HT
- ☐ PC35B40HF x 1-3/16"FB,KW2SS,HT
- ☐ PC35B42HF x 1-3/16"FB,KW2SS,HT
- ☐ PC35B45HF x 1-3/16"FB,KW2SS,HT

### #40 B-Hub Finished Bore Sprockets

- ☐ PC40B09HF x 1/2"FB,KW2SS,HT
- ☐ PC40B10HF x 1/2"FB,KW2SS,HT
- ☐ PC40B11HF x 1/2"FB,KW2SS,HT
- ☐ PC40B12HF x 1/2"FB,KW2SS,HT
- ☐ PC40B13HF x 1/2"FB,KW2SS,HT
- ☐ PC40B14HF x 1/2"FB,KW2SS,HT
- ☐ PC40B15HF x 1/2"FB,KW2SS,HT
- ☐ PC40B09HF x 5/8"FB,KW2SS,HT
- ☐ PC40B10HF x 5/8"FB,KW2SS,HT
- ☐ PC40B11HF x 5/8"FB,KW2SS,HT
- ☐ PC40B12HF x 5/8"FB,KW2SS,HT
- ☐ PC40B13HF x 5/8"FB,KW2SS,HT
- ☐ PC40B14HF x 5/8"FB,KW2SS,HT
- ☐ PC40B15HF x 5/8"FB,KW2SS,HT
- ☐ PC40B16HF x 5/8"FB,KW2SS,HT
- ☐ PC40B17HF x 5/8"FB,KW2SS,HT
- ☐ PC40B18HF x 5/8"FB,KW2SS,HT
- ☐ PC40B19HF x 5/8"FB,KW2SS,HT
- ☐ PC40B20HF x 5/8"FB,KW2SS,HT
- ☐ PC40B21HF x 5/8"FB,KW2SS,HT
- ☐ PC40B22HF x 5/8"FB,KW2SS,HT
- ☐ PC40B23HF x 5/8"FB,KW2SS,HT
- ☐ PC40B24HF x 5/8"FB,KW2SS,HT
- ☐ PC40B25HF x 5/8"FB,KW2SS,HT
- ☐ PC40B26HF x 5/8"FB,KW2SS,HT
- ☐ PC40B27HF x 5/8"FB,KW2SS,HT
- ☐ PC40B28HF x 5/8"FB,KW2SS,HT
- ☐ PC40B29HF x 5/8"FB,KW2SS,HT
- ☐ PC40B30HF x 5/8"FB,KW2SS,HT
- ☐ PC40B31HF x 5/8"FB,KW2SS,HT
- ☐ PC40B32HF x 5/8"FB,KW2SS,HT
- ☐ PC40B33HF x 5/8"FB,KW2SS,HT
- ☐ PC40B34HF x 5/8"FB,KW2SS,HT



|                                                      |                                                        |                                                         |
|------------------------------------------------------|--------------------------------------------------------|---------------------------------------------------------|
| <input type="checkbox"/> PC40B35HF x 5/8"FB,KW2SS,HT | <input type="checkbox"/> PC40B25HF x 7/8"FB,KW2SS,HT   | <input type="checkbox"/> PC40B33HF x 1-1/8"FB,KW2SS,HT  |
| <input type="checkbox"/> PC40B36HF x 5/8"FB,KW2SS,HT | <input type="checkbox"/> PC40B12HF x 1"FB,KW2SS,HT     | <input type="checkbox"/> PC40B34HF x 1-1/8"FB,KW2SS,HT  |
| <input type="checkbox"/> PC40B37HF x 5/8"FB,KW2SS,HT | <input type="checkbox"/> PC40B13HF x 1"FB,KW2SS,HT     | <input type="checkbox"/> PC40B35HF x 1-1/8"FB,KW2SS,HT  |
| <input type="checkbox"/> PC40B38HF x 5/8"FB,KW2SS,HT | <input type="checkbox"/> PC40B14HF x 1"FB,KW2SS,HT     | <input type="checkbox"/> PC40B36HF x 1-1/8"FB,KW2SS,HT  |
| <input type="checkbox"/> PC40B39HF x 5/8"FB,KW2SS,HT | <input type="checkbox"/> PC40B15HF x 1"FB,KW2SS,HT     | <input type="checkbox"/> PC40B37HF x 1-1/8"FB,KW2SS,HT  |
| <input type="checkbox"/> PC40B40HF x 5/8"FB,KW2SS,HT | <input type="checkbox"/> PC40B16HF x 1"FB,KW2SS,HT     | <input type="checkbox"/> PC40B38HF x 1-1/8"FB,KW2SS,HT  |
| <input type="checkbox"/> PC40B10HF x 3/4"FB,KW2SS,HT | <input type="checkbox"/> PC40B17HF x 1"FB,KW2SS,HT     | <input type="checkbox"/> PC40B39HF x 1-1/8"FB,KW2SS,HT  |
| <input type="checkbox"/> PC40B11HF x 3/4"FB,KW2SS,HT | <input type="checkbox"/> PC40B18HF x 1"FB,KW2SS,HT     | <input type="checkbox"/> PC40B40HF x 1-1/8"FB,KW2SS,HT  |
| <input type="checkbox"/> PC40B12HF x 3/4"FB,KW2SS,HT | <input type="checkbox"/> PC40B19HF x 1"FB,KW2SS,HT     | <input type="checkbox"/> PC40B42HF x 1-1/8"FB,KW2SS,HT  |
| <input type="checkbox"/> PC40B13HF x 3/4"FB,KW2SS,HT | <input type="checkbox"/> PC40B20HF x 1"FB,KW2SS,HT     | <input type="checkbox"/> PC40B45HF x 1-1/8"FB,KW2SS,HT  |
| <input type="checkbox"/> PC40B14HF x 3/4"FB,KW2SS,HT | <input type="checkbox"/> PC40B21HF x 1"FB,KW2SS,HT     | <input type="checkbox"/> PC40B48F x 1-1/8"FB,KW2SS      |
| <input type="checkbox"/> PC40B15HF x 3/4"FB,KW2SS,HT | <input type="checkbox"/> PC40B22HF x 1"FB,KW2SS,HT     | <input type="checkbox"/> PC40B54F x 1-1/8"FB,KW2SS      |
| <input type="checkbox"/> PC40B16HF x 3/4"FB,KW2SS,HT | <input type="checkbox"/> PC40B23HF x 1"FB,KW2SS,HT     | <input type="checkbox"/> PC40B60F x 1-1/8"FB,KW2SS      |
| <input type="checkbox"/> PC40B17HF x 3/4"FB,KW2SS,HT | <input type="checkbox"/> PC40B24HF x 1"FB,KW2SS,HT     | <input type="checkbox"/> PC40B15HF x 1-3/16"FB,KW2SS,HT |
| <input type="checkbox"/> PC40B18HF x 3/4"FB,KW2SS,HT | <input type="checkbox"/> PC40B25HF x 1"FB,KW2SS,HT     | <input type="checkbox"/> PC40B16HF x 1-3/16"FB,KW2SS,HT |
| <input type="checkbox"/> PC40B19HF x 3/4"FB,KW2SS,HT | <input type="checkbox"/> PC40B26HF x 1"FB,KW2SS,HT     | <input type="checkbox"/> PC40B17HF x 1-3/16"FB,KW2SS,HT |
| <input type="checkbox"/> PC40B20HF x 3/4"FB,KW2SS,HT | <input type="checkbox"/> PC40B27HF x 1"FB,KW2SS,HT     | <input type="checkbox"/> PC40B18HF x 1-3/16"FB,KW2SS,HT |
| <input type="checkbox"/> PC40B21HF x 3/4"FB,KW2SS,HT | <input type="checkbox"/> PC40B28HF x 1"FB,KW2SS,HT     | <input type="checkbox"/> PC40B19HF x 1-3/16"FB,KW2SS,HT |
| <input type="checkbox"/> PC40B22HF x 3/4"FB,KW2SS,HT | <input type="checkbox"/> PC40B29HF x 1"FB,KW2SS,HT     | <input type="checkbox"/> PC40B20HF x 1-3/16"FB,KW2SS,HT |
| <input type="checkbox"/> PC40B23HF x 3/4"FB,KW2SS,HT | <input type="checkbox"/> PC40B30HF x 1"FB,KW2SS,HT     | <input type="checkbox"/> PC40B21HF x 1-3/16"FB,KW2SS,HT |
| <input type="checkbox"/> PC40B24HF x 3/4"FB,KW2SS,HT | <input type="checkbox"/> PC40B31HF x 1"FB,KW2SS,HT     | <input type="checkbox"/> PC40B22HF x 1-3/16"FB,KW2SS,HT |
| <input type="checkbox"/> PC40B25HF x 3/4"FB,KW2SS,HT | <input type="checkbox"/> PC40B32HF x 1"FB,KW2SS,HT     | <input type="checkbox"/> PC40B23HF x 1-3/16"FB,KW2SS,HT |
| <input type="checkbox"/> PC40B26HF x 3/4"FB,KW2SS,HT | <input type="checkbox"/> PC40B33HF x 1"FB,KW2SS,HT     | <input type="checkbox"/> PC40B24HF x 1-3/16"FB,KW2SS,HT |
| <input type="checkbox"/> PC40B27HF x 3/4"FB,KW2SS,HT | <input type="checkbox"/> PC40B34HF x 1"FB,KW2SS,HT     | <input type="checkbox"/> PC40B25HF x 1-3/16"FB,KW2SS,HT |
| <input type="checkbox"/> PC40B28HF x 3/4"FB,KW2SS,HT | <input type="checkbox"/> PC40B35HF x 1"FB,KW2SS,HT     | <input type="checkbox"/> PC40B26HF x 1-3/16"FB,KW2SS,HT |
| <input type="checkbox"/> PC40B29HF x 3/4"FB,KW2SS,HT | <input type="checkbox"/> PC40B36HF x 1"FB,KW2SS,HT     | <input type="checkbox"/> PC40B27HF x 1-3/16"FB,KW2SS,HT |
| <input type="checkbox"/> PC40B30HF x 3/4"FB,KW2SS,HT | <input type="checkbox"/> PC40B37HF x 1"FB,KW2SS,HT     | <input type="checkbox"/> PC40B28HF x 1-3/16"FB,KW2SS,HT |
| <input type="checkbox"/> PC40B31HF x 3/4"FB,KW2SS,HT | <input type="checkbox"/> PC40B38HF x 1"FB,KW2SS,HT     | <input type="checkbox"/> PC40B29HF x 1-3/16"FB,KW2SS,HT |
| <input type="checkbox"/> PC40B32HF x 3/4"FB,KW2SS,HT | <input type="checkbox"/> PC40B39HF x 1"FB,KW2SS,HT     | <input type="checkbox"/> PC40B30HF x 1-3/16"FB,KW2SS,HT |
| <input type="checkbox"/> PC40B33HF x 3/4"FB,KW2SS,HT | <input type="checkbox"/> PC40B40HF x 1"FB,KW2SS,HT     | <input type="checkbox"/> PC40B31HF x 1-3/16"FB,KW2SS,HT |
| <input type="checkbox"/> PC40B34HF x 3/4"FB,KW2SS,HT | <input type="checkbox"/> PC40B42HF x 1"FB,KW2SS,HT     | <input type="checkbox"/> PC40B32HF x 1-3/16"FB,KW2SS,HT |
| <input type="checkbox"/> PC40B35HF x 3/4"FB,KW2SS,HT | <input type="checkbox"/> PC40B45HF x 1"FB,KW2SS,HT     | <input type="checkbox"/> PC40B33HF x 1-3/16"FB,KW2SS,HT |
| <input type="checkbox"/> PC40B36HF x 3/4"FB,KW2SS,HT | <input type="checkbox"/> PC40B48F x 1"FB,KW2SS         | <input type="checkbox"/> PC40B34HF x 1-3/16"FB,KW2SS,HT |
| <input type="checkbox"/> PC40B37HF x 3/4"FB,KW2SS,HT | <input type="checkbox"/> PC40B54F x 1"FB,KW2SS         | <input type="checkbox"/> PC40B35HF x 1-3/16"FB,KW2SS,HT |
| <input type="checkbox"/> PC40B38HF x 3/4"FB,KW2SS,HT | <input type="checkbox"/> PC40B60F x 1"FB,KW2SS         | <input type="checkbox"/> PC40B36HF x 1-3/16"FB,KW2SS,HT |
| <input type="checkbox"/> PC40B39HF x 3/4"FB,KW2SS,HT | <input type="checkbox"/> PC40B14HF x 1-1/8"FB,KW2SS,HT | <input type="checkbox"/> PC40B37HF x 1-3/16"FB,KW2SS,HT |
| <input type="checkbox"/> PC40B40HF x 3/4"FB,KW2SS,HT | <input type="checkbox"/> PC40B15HF x 1-1/8"FB,KW2SS,HT | <input type="checkbox"/> PC40B38HF x 1-3/16"FB,KW2SS,HT |
| <input type="checkbox"/> PC40B42HF x 3/4"FB,KW2SS,HT | <input type="checkbox"/> PC40B16HF x 1-1/8"FB,KW2SS,HT | <input type="checkbox"/> PC40B39HF x 1-3/16"FB,KW2SS,HT |
| <input type="checkbox"/> PC40B45HF x 3/4"FB,KW2SS,HT | <input type="checkbox"/> PC40B17HF x 1-1/8"FB,KW2SS,HT | <input type="checkbox"/> PC40B40HF x 1-3/16"FB,KW2SS,HT |
| <input type="checkbox"/> PC40B48F x 3/4"FB,KW2SS     | <input type="checkbox"/> PC40B18HF x 1-1/8"FB,KW2SS,HT | <input type="checkbox"/> PC40B42HF x 1-3/16"FB,KW2SS,HT |
| <input type="checkbox"/> PC40B11HF x 7/8"FB,KW2SS,HT | <input type="checkbox"/> PC40B19HF x 1-1/8"FB,KW2SS,HT | <input type="checkbox"/> PC40B45HF x 1-3/16"FB,KW2SS,HT |
| <input type="checkbox"/> PC40B12HF x 7/8"FB,KW2SS,HT | <input type="checkbox"/> PC40B20HF x 1-1/8"FB,KW2SS,HT | <input type="checkbox"/> PC40B48F x 1-3/16"FB,KW2SS     |
| <input type="checkbox"/> PC40B13HF x 7/8"FB,KW2SS,HT | <input type="checkbox"/> PC40B21HF x 1-1/8"FB,KW2SS,HT | <input type="checkbox"/> PC40B54F x 1-3/16"FB,KW2SS     |
|                                                      |                                                        |                                                         |

## PEER Chain Sprockets

|                                          |                               |                          |                             |                          |                                |
|------------------------------------------|-------------------------------|--------------------------|-----------------------------|--------------------------|--------------------------------|
| <input type="checkbox"/>                 | PC40B25HF x 1-1/4"FB,KW2SS,HT | <input type="checkbox"/> | PC50B14HF x 3/4"FB,KW2SS,HT | <input type="checkbox"/> | PC50B30HF x 1"FB,KW2SS,HT      |
| <input type="checkbox"/>                 | PC40B26HF x 1-1/4"FB,KW2SS,HT | <input type="checkbox"/> | PC50B15HF x 3/4"FB,KW2SS,HT | <input type="checkbox"/> | PC50B31HF x 1"FB,KW2SS,HT      |
| <input type="checkbox"/>                 | PC40B27HF x 1-1/4"FB,KW2SS,HT | <input type="checkbox"/> | PC50B16HF x 3/4"FB,KW2SS,HT | <input type="checkbox"/> | PC50B32HF x 1"FB,KW2SS,HT      |
| <input type="checkbox"/>                 | PC40B28HF x 1-1/4"FB,KW2SS,HT | <input type="checkbox"/> | PC50B17HF x 3/4"FB,KW2SS,HT | <input type="checkbox"/> | PC50B33HF x 1"FB,KW2SS,HT      |
| <input type="checkbox"/>                 | PC40B29HF x 1-1/4"FB,KW2SS,HT | <input type="checkbox"/> | PC50B18HF x 3/4"FB,KW2SS,HT | <input type="checkbox"/> | PC50B34HF x 1"FB,KW2SS,HT      |
| <input type="checkbox"/>                 | PC40B30HF x 1-1/4"FB,KW2SS,HT | <input type="checkbox"/> | PC50B19HF x 3/4"FB,KW2SS,HT | <input type="checkbox"/> | PC50B35HF x 1"FB,KW2SS,HT      |
| <input type="checkbox"/>                 | PC40B34HF x 1-1/4"FB,KW2SS,HT | <input type="checkbox"/> | PC50B20HF x 3/4"FB,KW2SS,HT | <input type="checkbox"/> | PC50B36HF x 1"FB,KW2SS,HT      |
| <input type="checkbox"/>                 | PC40B36HF x 1-1/4"FB,KW2SS,HT | <input type="checkbox"/> | PC50B21HF x 3/4"FB,KW2SS,HT | <input type="checkbox"/> | PC50B40F x 1"FB,KW2SS          |
| <input type="checkbox"/>                 | PC40B40HF x 1-1/4"FB,KW2SS,HT | <input type="checkbox"/> | PC50B22HF x 3/4"FB,KW2SS,HT | <input type="checkbox"/> | PC50B42F x 1"FB,KW2SS          |
| <input type="checkbox"/>                 | PC40B42HF x 1-1/4"FB,KW2SS,HT | <input type="checkbox"/> | PC50B23HF x 3/4"FB,KW2SS,HT | <input type="checkbox"/> | PC50B45F x 1"FB,KW2SS          |
| <input type="checkbox"/>                 | PC40B45HF x 1-1/4"FB,KW2SS,HT | <input type="checkbox"/> | PC50B24HF x 3/4"FB,KW2SS,HT | <input type="checkbox"/> | PC50B48F x 1"FB,KW2SS          |
| <input type="checkbox"/>                 | PC40B48F x 1-1/4"FB,KW2SS     | <input type="checkbox"/> | PC50B25HF x 3/4"FB,KW2SS,HT | <input type="checkbox"/> | PC50B54F x 1"FB,KW2SS          |
| <input type="checkbox"/>                 | PC40B54F x 1-1/4"FB,KW2SS     | <input type="checkbox"/> | PC50B26HF x 3/4"FB,KW2SS,HT | <input type="checkbox"/> | PC50B60F x 1"FB,KW2SS          |
| <input type="checkbox"/>                 | PC40B60F x 1-1/4"FB,KW2SS     | <input type="checkbox"/> | PC50B27HF x 3/4"FB,KW2SS,HT | <input type="checkbox"/> | PC50B72F x 1"FB,KW2SS          |
| <input type="checkbox"/>                 | PC40B18HF x 1-1/2"FB,KW2SS,HT | <input type="checkbox"/> | PC50B28HF x 3/4"FB,KW2SS,HT | <input type="checkbox"/> | PC50B12HF x 1-1/8"FB,KW2SS,HT  |
| <input type="checkbox"/>                 | PC40B19HF x 1-1/2"FB,KW2SS,HT | <input type="checkbox"/> | PC50B29HF x 3/4"FB,KW2SS,HT | <input type="checkbox"/> | PC50B13HF x 1-1/8"FB,KW2SS,HT  |
| <input type="checkbox"/>                 | PC40B20HF x 1-1/2"FB,KW2SS,HT | <input type="checkbox"/> | PC50B30HF x 3/4"FB,KW2SS,HT | <input type="checkbox"/> | PC50B14HF x 1-1/8"FB,KW2SS,HT  |
| <input type="checkbox"/>                 | PC40B21HF x 1-1/2"FB,KW2SS,HT | <input type="checkbox"/> | PC50B10HF x 7/8"FB,KW2SS,HT | <input type="checkbox"/> | PC50B15HF x 1-1/8"FB,KW2SS,HT  |
| <input type="checkbox"/>                 | PC40B22HF x 1-1/2"FB,KW2SS,HT | <input type="checkbox"/> | PC50B11HF x 7/8"FB,KW2SS,HT | <input type="checkbox"/> | PC50B16HF x 1-1/8"FB,KW2SS,HT  |
| <input type="checkbox"/>                 | PC40B23HF x 1-1/2"FB,KW2SS,HT | <input type="checkbox"/> | PC50B12HF x 7/8"FB,KW2SS,HT | <input type="checkbox"/> | PC50B17HF x 1-1/8"FB,KW2SS,HT  |
| <input type="checkbox"/>                 | PC40B24HF x 1-1/2"FB,KW2SS,HT | <input type="checkbox"/> | PC50B13HF x 7/8"FB,KW2SS,HT | <input type="checkbox"/> | PC50B18HF x 1-1/8"FB,KW2SS,HT  |
| <input type="checkbox"/>                 | PC40B25HF x 1-1/2"FB,KW2SS,HT | <input type="checkbox"/> | PC50B14HF x 7/8"FB,KW2SS,HT | <input type="checkbox"/> | PC50B19HF x 1-1/8"FB,KW2SS,HT  |
| <input type="checkbox"/>                 | PC40B26HF x 1-1/2"FB,KW2SS,HT | <input type="checkbox"/> | PC50B15HF x 7/8"FB,KW2SS,HT | <input type="checkbox"/> | PC50B20HF x 1-1/8"FB,KW2SS,HT  |
| <input type="checkbox"/>                 | PC40B27HF x 1-1/2"FB,KW2SS,HT | <input type="checkbox"/> | PC50B16HF x 7/8"FB,KW2SS,HT | <input type="checkbox"/> | PC50B21HF x 1-1/8"FB,KW2SS,HT  |
| <input type="checkbox"/>                 | PC40B28HF x 1-1/2"FB,KW2SS,HT | <input type="checkbox"/> | PC50B17HF x 7/8"FB,KW2SS,HT | <input type="checkbox"/> | PC50B22HF x 1-1/8"FB,KW2SS,HT  |
| <input type="checkbox"/>                 | PC40B29HF x 1-1/2"FB,KW2SS,HT | <input type="checkbox"/> | PC50B18HF x 7/8"FB,KW2SS,HT | <input type="checkbox"/> | PC50B23HF x 1-1/8"FB,KW2SS,HT  |
| <input type="checkbox"/>                 | PC40B30HF x 1-1/2"FB,KW2SS,HT | <input type="checkbox"/> | PC50B19HF x 7/8"FB,KW2SS,HT | <input type="checkbox"/> | PC50B24HF x 1-1/8"FB,KW2SS,HT  |
| <input type="checkbox"/>                 | PC40B34HF x 1-1/2"FB,KW2SS,HT | <input type="checkbox"/> | PC50B20HF x 7/8"FB,KW2SS,HT | <input type="checkbox"/> | PC50B25HF x 1-1/8"FB,KW2SS,HT  |
| <input type="checkbox"/>                 | PC40B36HF x 1-1/2"FB,KW2SS,HT | <input type="checkbox"/> | PC50B21HF x 7/8"FB,KW2SS,HT | <input type="checkbox"/> | PC50B26HF x 1-1/8"FB,KW2SS,HT  |
| <input type="checkbox"/>                 | PC40B40HF x 1-1/2"FB,KW2SS,HT | <input type="checkbox"/> | PC50B22HF x 7/8"FB,KW2SS,HT | <input type="checkbox"/> | PC50B27HF x 1-1/8"FB,KW2SS,HT  |
| <input type="checkbox"/>                 | PC40B42HF x 1-1/2"FB,KW2SS,HT | <input type="checkbox"/> | PC50B23HF x 7/8"FB,KW2SS,HT | <input type="checkbox"/> | PC50B28HF x 1-1/8"FB,KW2SS,HT  |
| <input type="checkbox"/>                 | PC40B45HF x 1-1/2"FB,KW2SS,HT | <input type="checkbox"/> | PC50B24HF x 7/8"FB,KW2SS,HT | <input type="checkbox"/> | PC50B29HF x 1-1/8"FB,KW2SS,HT  |
| <input type="checkbox"/>                 | PC40B48F x 1-1/2"FB,KW2SS     | <input type="checkbox"/> | PC50B25HF x 7/8"FB,KW2SS,HT | <input type="checkbox"/> | PC50B30HF x 1-1/8"FB,KW2SS,HT  |
| <input type="checkbox"/>                 | PC40B54F x 1-1/2"FB,KW2SS     | <input type="checkbox"/> | PC50B26HF x 7/8"FB,KW2SS,HT | <input type="checkbox"/> | PC50B31HF x 1-1/8"FB,KW2SS,HT  |
| <input type="checkbox"/>                 | PC40B60F x 1-1/2"FB,KW2SS     | <input type="checkbox"/> | PC50B10HF x 1"FB,KW2SS,HT   | <input type="checkbox"/> | PC50B32HF x 1-1/8"FB,KW2SS,HT  |
| <b>#50 B-Hub Finished Bore Sprockets</b> |                               | <input type="checkbox"/> | PC50B11HF x 1"FB,KW2SS,HT   | <input type="checkbox"/> | PC50B33HF x 1-1/8"FB,KW2SS,HT  |
| <input type="checkbox"/>                 | PC50B09HF x 5/8"FB,KW2SS,HT   | <input type="checkbox"/> | PC50B12HF x 1"FB,KW2SS,HT   | <input type="checkbox"/> | PC50B34HF x 1-1/8"FB,KW2SS,HT  |
| <input type="checkbox"/>                 | PC50B10HF x 5/8"FB,KW2SS,HT   | <input type="checkbox"/> | PC50B13HF x 1"FB,KW2SS,HT   | <input type="checkbox"/> | PC50B35HF x 1-1/8"FB,KW2SS,HT  |
| <input type="checkbox"/>                 | PC50B11HF x 5/8"FB,KW2SS,HT   | <input type="checkbox"/> | PC50B14HF x 1"FB,KW2SS,HT   | <input type="checkbox"/> | PC50B36HF x 1-1/8"FB,KW2SS,HT  |
| <input type="checkbox"/>                 | PC50B12HF x 5/8"FB,KW2SS,HT   | <input type="checkbox"/> | PC50B15HF x 1"FB,KW2SS,HT   | <input type="checkbox"/> | PC50B40F x 1-1/8"FB,KW2SS      |
| <input type="checkbox"/>                 | PC50B13HF x 5/8"FB,KW2SS,HT   | <input type="checkbox"/> | PC50B16HF x 1"FB,KW2SS,HT   | <input type="checkbox"/> | PC50B42F x 1-1/8"FB,KW2SS      |
| <input type="checkbox"/>                 | PC50B14HF x 5/8"FB,KW2SS,HT   | <input type="checkbox"/> | PC50B17HF x 1"FB,KW2SS,HT   | <input type="checkbox"/> | PC50B45F x 1-1/8"FB,KW2SS      |
| <input type="checkbox"/>                 | PC50B15HF x 5/8"FB,KW2SS,HT   | <input type="checkbox"/> | PC50B18HF x 1"FB,KW2SS,HT   | <input type="checkbox"/> | PC50B48F x 1-1/8"FB,KW2SS      |
| <input type="checkbox"/>                 | PC50B16HF x 5/8"FB,KW2SS,HT   | <input type="checkbox"/> | PC50B19HF x 1"FB,KW2SS,HT   | <input type="checkbox"/> | PC50B54F x 1-1/8"FB,KW2SS      |
| <input type="checkbox"/>                 | PC50B17HF x 5/8"FB,KW2SS,HT   | <input type="checkbox"/> | PC50B20HF x 1"FB,KW2SS,HT   | <input type="checkbox"/> | PC50B60F x 1-1/8"FB,KW2SS      |
| <input type="checkbox"/>                 | PC50B18HF x 5/8"FB,KW2SS,HT   | <input type="checkbox"/> | PC50B21HF x 1"FB,KW2SS,HT   | <input type="checkbox"/> | PC50B72F x 1-1/8"FB,KW2SS      |
| <input type="checkbox"/>                 | PC50B19HF x 5/8"FB,KW2SS,HT   | <input type="checkbox"/> | PC50B22HF x 1"FB,KW2SS,HT   | <input type="checkbox"/> | PC50B12HF x 1-3/16"FB,KW2SS,HT |
| <input type="checkbox"/>                 | PC50B20HF x 5/8"FB,KW2SS,HT   | <input type="checkbox"/> | PC50B23HF x 1"FB,KW2SS,HT   | <input type="checkbox"/> | PC50B13HF x 1-3/16"FB,KW2SS,HT |
| <input type="checkbox"/>                 | PC50B09HF x 3/4"FB,KW2SS,HT   | <input type="checkbox"/> | PC50B24HF x 1"FB,KW2SS,HT   | <input type="checkbox"/> | PC50B14HF x 1-3/16"FB,KW2SS,HT |
| <input type="checkbox"/>                 | PC50B10HF x 3/4"FB,KW2SS,HT   | <input type="checkbox"/> | PC50B25HF x 1"FB,KW2SS,HT   | <input type="checkbox"/> | PC50B15HF x 1-3/16"FB,KW2SS,HT |
| <input type="checkbox"/>                 | PC50B11HF x 3/4"FB,KW2SS,HT   | <input type="checkbox"/> | PC50B26HF x 1"FB,KW2SS,HT   | <input type="checkbox"/> | PC50B16HF x 1-3/16"FB,KW2SS,HT |
| <input type="checkbox"/>                 | PC50B12HF x 3/4"FB,KW2SS,HT   | <input type="checkbox"/> | PC50B27HF x 1"FB,KW2SS,HT   | <input type="checkbox"/> | PC50B17HF x 1-3/16"FB,KW2SS,HT |
| <input type="checkbox"/>                 | PC50B13HF x 3/4"FB,KW2SS,HT   | <input type="checkbox"/> | PC50B28HF x 1"FB,KW2SS,HT   | <input type="checkbox"/> | PC50B18HF x 1-3/16"FB,KW2SS,HT |
| <input type="checkbox"/>                 |                               | <input type="checkbox"/> | PC50B29HF x 1"FB,KW2SS,HT   | <input type="checkbox"/> | PC50B19HF x 1-3/16"FB,KW2SS,HT |

## PEER Chain Sprockets

|                                                         |                                                         |                                                        |
|---------------------------------------------------------|---------------------------------------------------------|--------------------------------------------------------|
| <input type="checkbox"/> PC50B20HF x 1-3/16"FB,KW2SS,HT | <input type="checkbox"/> PC50B60F x 1-1/4"FB,KW2SS      | <input type="checkbox"/> PC50B30HFX1-1/2"FB,KW2SS,HT   |
| <input type="checkbox"/> PC50B21HF x 1-3/16"FB,KW2SS,HT | <input type="checkbox"/> PC50B72F x 1-1/4"FB,KW2SS      | <input type="checkbox"/> PC50B31HF x 1-1/2"FB,KW2SS,HT |
| <input type="checkbox"/> PC50B22HF x 1-3/16"FB,KW2SS,HT | <input type="checkbox"/> PC50B15HF x 1-3/8"FB,KW2SS,HT  | <input type="checkbox"/> PC50B32HF x 1-1/2"FB,KW2SS,HT |
| <input type="checkbox"/> PC50B23HFX1-3/16"FB,KW2SS,HT   | <input type="checkbox"/> PC50B16HF x 1-3/8"FB,KW2SS,HT  | <input type="checkbox"/> PC50B33HF x 1-1/2"FB,KW2SS,HT |
| <input type="checkbox"/> PC50B24HF x 1-3/16"FB,KW2SS,HT | <input type="checkbox"/> PC50B17HF x 1-3/8"FB,KW2SS,HT  | <input type="checkbox"/> PC50B34HF x 1-1/2"FB,KW2SS,HT |
| <input type="checkbox"/> PC50B25HF x 1-3/16"FB,KW2SS,HT | <input type="checkbox"/> PC50B18HF x 1-3/8"FB,KW2SS,HT  | <input type="checkbox"/> PC50B35HF x 1-1/2"FB,KW2SS,HT |
| <input type="checkbox"/> PC50B26HF x 1-3/16"FB,KW2SS,HT | <input type="checkbox"/> PC50B19HF x 1-3/8"FB,KW2SS,HT  | <input type="checkbox"/> PC50B36HF x 1-1/2"FB,KW2SS,HT |
| <input type="checkbox"/> PC50B27HF x 1-3/16"FB,KW2SS,HT | <input type="checkbox"/> PC50B20HF x 1-3/8"FB,KW2SS,HT  | <input type="checkbox"/> PC50B40F x 1-1/2"FB,KW2SS     |
| <input type="checkbox"/> PC50B28HF x 1-3/16"FB,KW2SS,HT | <input type="checkbox"/> PC50B21HF x 1-3/8"FB,KW2SS,HT  | <input type="checkbox"/> PC50B42F x 1-1/2"FB,KW2SS     |
| <input type="checkbox"/> PC50B29HF x 1-3/16"FB,KW2SS,HT | <input type="checkbox"/> PC50B22HF x 1-3/8"FB,KW2SS,HT  | <input type="checkbox"/> PC50B45F x 1-1/2"FB,KW2SS     |
| <input type="checkbox"/> PC50B30HF x 1-3/16"FB,KW2SS,HT | <input type="checkbox"/> PC50B15HF x 1-7/16"FB,KW2SS,HT | <input type="checkbox"/> PC50B48F x 1-1/2"FB,KW2SS     |
| <input type="checkbox"/> PC50B31HF x 1-3/16"FB,KW2SS,HT | <input type="checkbox"/> PC50B16HF x 1-7/16"FB,KW2SS,HT | <input type="checkbox"/> PC50B54F x 1-1/2"FB,KW2SS     |
| <input type="checkbox"/> PC50B32HF x 1-3/16"FB,KW2SS,HT | <input type="checkbox"/> PC50B17HF x 1-7/16"FB,KW2SS,HT | <input type="checkbox"/> PC50B60F x 1-1/2"FB,KW2SS     |
| <input type="checkbox"/> PC50B33HF x 1-3/16"FB,KW2SS,HT | <input type="checkbox"/> PC50B18HF x 1-7/16"FB,KW2SS,HT | <input type="checkbox"/> PC50B72F x 1-1/2"FB,KW2SS     |
| <input type="checkbox"/> PC50B34HF x 1-3/16"FB,KW2SS,HT | <input type="checkbox"/> PC50B19HF x 1-7/16"FB,KW2SS,HT |                                                        |
| <input type="checkbox"/> PC50B35HF x 1-3/16"FB,KW2SS,HT | <input type="checkbox"/> PC50B20HF x 1-7/16"FB,KW2SS,HT | <b>#60 B-Hub Finished Bore Sprockets</b>               |
| <input type="checkbox"/> PC50B36HF x 1-3/16"FB,KW2SS,HT | <input type="checkbox"/> PC50B21HF x 1-7/16"FB,KW2SS,HT | <input type="checkbox"/> PC60B09HF x 3/4"FB,KW2SS,HT   |
| <input type="checkbox"/> PC50B40F x 1-3/16"FB,KW2SS     | <input type="checkbox"/> PC50B22HF x 1-7/16"FB,KW2SS,HT | <input type="checkbox"/> PC60B10HF x 3/4"FB,KW2SS,HT   |
| <input type="checkbox"/> PC50B42F x 1-3/16"FB,KW2SS     | <input type="checkbox"/> PC50B23HF x 1-7/16"FB,KW2SS,HT | <input type="checkbox"/> PC60B11HF x 3/4"FB,KW2SS,HT   |
| <input type="checkbox"/> PC50B45F x 1-3/16"FB,KW2SS     | <input type="checkbox"/> PC50B24HF x 1-7/16"FB,KW2SS,HT | <input type="checkbox"/> PC60B12HF x 3/4"FB,KW2SS,HT   |
| <input type="checkbox"/> PC50B48F x 1-3/16"FB,KW2SS     | <input type="checkbox"/> PC50B25HF x 1-7/16"FB,KW2SS,HT | <input type="checkbox"/> PC60B13HF x 3/4"FB,KW2SS,HT   |
| <input type="checkbox"/> PC50B54F x 1-3/16"FB,KW2SS     | <input type="checkbox"/> PC50B26HF x 1-7/16"FB,KW2SS,HT | <input type="checkbox"/> PC60B14HF x 3/4"FB,KW2SS,HT   |
| <input type="checkbox"/> PC50B60F x 1-3/16"FB,KW2SS     | <input type="checkbox"/> PC50B27HF x 1-7/16"FB,KW2SS,HT | <input type="checkbox"/> PC60B15HF x 3/4"FB,KW2SS,HT   |
| <input type="checkbox"/> PC50B72F x 1-3/16"FB,KW2SS     | <input type="checkbox"/> PC50B28HF x 1-7/16"FB,KW2SS,HT | <input type="checkbox"/> PC60B16HF x 3/4"FB,KW2SS,HT   |
| <input type="checkbox"/> PC50B12HF x 1-1/4"FB,KW2SS,HT  | <input type="checkbox"/> PC50B29HF x 1-7/16"FB,KW2SS,HT | <input type="checkbox"/> PC60B09HF x 7/8"FB,KW2SS,HT   |
| <input type="checkbox"/> PC50B13HF x 1-1/4"FB,KW2SS,HT  | <input type="checkbox"/> PC50B30HF x 1-7/16"FB,KW2SS,HT | <input type="checkbox"/> PC60B10HF x 7/8"FB,KW2SS,HT   |
| <input type="checkbox"/> PC50B14HF x 1-1/4"FB,KW2SS,HT  | <input type="checkbox"/> PC50B31HF x 1-7/16"FB,KW2SS,HT | <input type="checkbox"/> PC60B11HF x 7/8"FB,KW2SS,HT   |
| <input type="checkbox"/> PC50B15HF x 1-1/4"FB,KW2SS,HT  | <input type="checkbox"/> PC50B32HF x 1-7/16"FB,KW2SS,HT | <input type="checkbox"/> PC60B12HF x 7/8"FB,KW2SS,HT   |
| <input type="checkbox"/> PC50B16HF x 1-1/4"FB,KW2SS,HT  | <input type="checkbox"/> PC50B33HF x 1-7/16"FB,KW2SS,HT | <input type="checkbox"/> PC60B13HF x 7/8"FB,KW2SS,HT   |
| <input type="checkbox"/> PC50B17HF x 1-1/4"FB,KW2SS,HT  | <input type="checkbox"/> PC50B34HF x 1-7/16"FB,KW2SS,HT | <input type="checkbox"/> PC60B14HF x 7/8"FB,KW2SS,HT   |
| <input type="checkbox"/> PC50B18HF x 1-1/4"FB,KW2SS,HT  | <input type="checkbox"/> PC50B35HF x 1-7/16"FB,KW2SS,HT | <input type="checkbox"/> PC60B15HF x 7/8"FB,KW2SS,HT   |
| <input type="checkbox"/> PC50B19HF x 1-1/4"FB,KW2SS,HT  | <input type="checkbox"/> PC50B36HF x 1-7/16"FB,KW2SS,HT | <input type="checkbox"/> PC60B16HF x 7/8"FB,KW2SS,HT   |
| <input type="checkbox"/> PC50B20HF x 1-1/4"FB,KW2SS,HT  | <input type="checkbox"/> PC50B40F x 1-7/16"FB,KW2SS     | <input type="checkbox"/> PC60B09HF x 1"FB,KW2SS,HT     |
| <input type="checkbox"/> PC50B21HF x 1-1/4"FB,KW2SS,HT  | <input type="checkbox"/> PC50B42F x 1-7/16"FB,KW2SS     | <input type="checkbox"/> PC60B10HF x 1"FB,KW2SS,HT     |
| <input type="checkbox"/> PC50B22HF x 1-1/4"FB,KW2SS,HT  | <input type="checkbox"/> PC50B45F x 1-7/16"FB,KW2SS     | <input type="checkbox"/> PC60B11HF x 1"FB,KW2SS,HT     |
| <input type="checkbox"/> PC50B23HF x 1-1/4"FB,KW2SS,HT  | <input type="checkbox"/> PC50B48F x 1-7/16"FB,KW2SS     | <input type="checkbox"/> PC60B12HF x 1"FB,KW2SS,HT     |
| <input type="checkbox"/> PC50B24HF x 1-1/4"FB,KW2SS,HT  | <input type="checkbox"/> PC50B54F x 1-7/16"FB,KW2SS     | <input type="checkbox"/> PC60B13HF x 1"FB,KW2SS,HT     |
| <input type="checkbox"/> PC50B25HF x 1-1/4"FB,KW2SS,HT  | <input type="checkbox"/> PC50B60F x 1-7/16"FB,KW2SS     | <input type="checkbox"/> PC60B14HF x 1"FB,KW2SS,HT     |
| <input type="checkbox"/> PC50B26HF x 1-1/4"FB,KW2SS,HT  | <input type="checkbox"/> PC50B72F x 1-7/16"FB,KW2SS     | <input type="checkbox"/> PC60B15HF x 1"FB,KW2SS,HT     |
| <input type="checkbox"/> PC50B27HF x 1-1/4"FB,KW2SS,HT  | <input type="checkbox"/> PC50B15HF x 1-1/2"FB,KW2SS,HT  | <input type="checkbox"/> PC60B16HF x 1"FB,KW2SS,HT     |
| <input type="checkbox"/> PC50B28HF x 1-1/4"FB,KW2SS,HT  | <input type="checkbox"/> PC50B16HF x 1-1/2"FB,KW2SS,HT  | <input type="checkbox"/> PC60B17HF x 1"FB,KW2SS,HT     |
| <input type="checkbox"/> PC50B29HF x 1-1/4"FB,KW2SS,HT  | <input type="checkbox"/> PC50B17HF x 1-1/2"FB,KW2SS,HT  | <input type="checkbox"/> PC60B18HF x 1"FB,KW2SS,HT     |
| <input type="checkbox"/> PC50B30HF x 1-1/4"FB,KW2SS,HT  | <input type="checkbox"/> PC50B18HFX1-1/2"FB,KW2SS,HT    | <input type="checkbox"/> PC60B19HF x 1"FB,KW2SS,HT     |
| <input type="checkbox"/> PC50B31HF x 1-1/4"FB,KW2SS,HT  | <input type="checkbox"/> PC50B19HFX1-1/2"FB,KW2SS,HT    | <input type="checkbox"/> PC60B20HF x 1"FB,KW2SS,HT     |
| <input type="checkbox"/> PC50B32HF x 1-1/4"FB,KW2SS,HT  | <input type="checkbox"/> PC50B20HFX1-1/2"FB,KW2SS,HT    | <input type="checkbox"/> PC60B21HF x 1"FB,KW2SS,HT     |
| <input type="checkbox"/> PC50B33HF x 1-1/4"FB,KW2SS,HT  | <input type="checkbox"/> PC50B21HFX1-1/2"FB,KW2SS,HT    | <input type="checkbox"/> PC60B22HF x 1"FB,KW2SS,HT     |
| <input type="checkbox"/> PC50B34HF x 1-1/4"FB,KW2SS,HT  | <input type="checkbox"/> PC50B22HFX1-1/2"FB,KW2SS,HT    | <input type="checkbox"/> PC60B23HF x 1"FB,KW2SS,HT     |
| <input type="checkbox"/> PC50B35HFX1-1/4"FB,KW2SS,HT    | <input type="checkbox"/> PC50B23HFX1-1/2"FB,KW2SS,HT    | <input type="checkbox"/> PC60B24HF x 1"FB,KW2SS,HT     |
| <input type="checkbox"/> PC50B36HFX1-1/4"FB,KW2SS,HT    | <input type="checkbox"/> PC50B24HFX1-1/2"FB,KW2SS,HT    | <input type="checkbox"/> PC60B25HF x 1"FB,KW2SS,HT     |
| <input type="checkbox"/> PC50B40F x 1-1/4"FB,KW2SS      | <input type="checkbox"/> PC50B25HFX1-1/2"FB,KW2SS,HT    | <input type="checkbox"/> PC60B26HF x 1"FB,KW2SS,HT     |
| <input type="checkbox"/> PC50B42F x 1-1/4"FB,KW2SS      | <input type="checkbox"/> PC50B26HFX1-1/2"FB,KW2SS,HT    | <input type="checkbox"/> PC60B27HF x 1"FB,KW2SS,HT     |
| <input type="checkbox"/> PC50B45F x 1-1/4"FB,KW2SS      | <input type="checkbox"/> PC50B27HFX1-1/2"FB,KW2SS,HT    | <input type="checkbox"/> PC60B28HF x 1"FB,KW2SS,HT     |
| <input type="checkbox"/> PC50B48F x 1-1/4"FB,KW2SS      | <input type="checkbox"/> PC50B28HFX1-1/2"FB,KW2SS,HT    | <input type="checkbox"/> PC60B29HF x 1"FB,KW2SS,HT     |
| <input type="checkbox"/> PC50B54F x 1-1/4"FB,KW2SS      | <input type="checkbox"/> PC50B29HFX1-1/2"FB,KW2SS,HT    | <input type="checkbox"/> PC60B30HF x 1"FB,KW2SS,HT     |



☐ PC60B10HF x 1-1/8"FB,KW2SS,HT  
☐ PC60B11HF x 1-1/8"FB,KW2SS,HT  
☐ PC60B12HF x 1-1/8"FB,KW2SS,HT  
☐ PC60B13HF x 1-1/8"FB,KW2SS,HT  
☐ PC60B14HF x 1-1/8"FB,KW2SS,HT  
☐ PC60B15HF x 1-1/8"FB,KW2SS,HT  
☐ PC60B16HF x 1-1/8"FB,KW2SS,HT  
☐ PC60B17HF x 1-1/8"FB,KW2SS,HT  
☐ PC60B18HF x 1-1/8"FB,KW2SS,HT  
☐ PC60B19HF x 1-1/8"FB,KW2SS,HT  
☐ PC60B20HF x 1-1/8"FB,KW2SS,HT  
☐ PC60B21HF x 1-1/8"FB,KW2SS,HT  
☐ PC60B22HF x 1-1/8"FB,KW2SS,HT  
☐ PC60B23HF x 1-1/8"FB,KW2SS,HT  
☐ PC60B24HF x 1-1/8"FB,KW2SS,HT  
☐ PC60B25HF x 1-1/8"FB,KW2SS,HT  
☐ PC60B26HF x 1-1/8"FB,KW2SS,HT  
☐ PC60B30HF x 1-1/8"FB,KW2SS,HT  
☐ PC60B10HF x 1-3/16"FB,KW2SS,HT  
☐ PC60B11HF x 1-3/16"FB,KW2SS,HT  
☐ PC60B12HF x 1-3/16"FB,KW2SS,HT  
☐ PC60B13HF x 1-3/16"FB,KW2SS,HT  
☐ PC60B14HF x 1-3/16"FB,KW2SS,HT  
☐ PC60B15HF x 1-3/16"FB,KW2SS,HT  
☐ PC60B16HF x 1-3/16"FB,KW2SS,HT  
☐ PC60B17HF x 1-3/16"FB,KW2SS,HT  
☐ PC60B18HF x 1-3/16"FB,KW2SS,HT  
☐ PC60B19HF x 1-3/16"FB,KW2SS,HT  
☐ PC60B20HF x 1-3/16"FB,KW2SS,HT  
☐ PC60B21HF x 1-3/16"FB,KW2SS,HT  
☐ PC60B22HF x 1-3/16"FB,KW2SS,HT  
☐ PC60B23HF x 1-3/16"FB,KW2SS,HT  
☐ PC60B24HF x 1-3/16"FB,KW2SS,HT  
☐ PC60B25HF x 1-3/16"FB,KW2SS,HT  
☐ PC60B26HF x 1-3/16"FB,KW2SS,HT  
☐ PC60B30HF x 1-3/16"FB,KW2SS,HT  
☐ PC60B10HF x 1-1/4"FB,KW2SS,HT  
☐ PC60B11HF x 1-1/4"FB,KW2SS,HT  
☐ PC60B12HF x 1-1/4"FB,KW2SS,HT  
☐ PC60B13HF x 1-1/4"FB,KW2SS,HT  
☐ PC60B14HF x 1-1/4"FB,KW2SS,HT  
☐ PC60B15HF x 1-1/4"FB,KW2SS,HT  
☐ PC60B16HF x 1-1/4"FB,KW2SS,HT  
☐ PC60B17HF x 1-1/4"FB,KW2SS,HT  
☐ PC60B18HF x 1-1/4"FB,KW2SS,HT  
☐ PC60B19HF x 1-1/4"FB,KW2SS,HT  
☐ PC60B20HF x 1-1/4"FB,KW2SS,HT  
☐ PC60B21HF x 1-1/4"FB,KW2SS,HT  
☐ PC60B22HF x 1-1/4"FB,KW2SS,HT  
☐ PC60B23HF x 1-1/4"FB,KW2SS,HT  
☐ PC60B24HF x 1-1/4"FB,KW2SS,HT  
☐ PC60B25HF x 1-1/4"FB,KW2SS,HT  
☐ PC60B26HF x 1-1/4"FB,KW2SS,HT  
☐ PC60B27HF x 1-1/4"FB,KW2SS,HT

☐ PC60B28HF x 1-1/4"FB,KW2SS,HT  
☐ PC60B29HF x 1-1/4"FB,KW2SS,HT  
☐ PC60B30HF x 1-1/4"FB,KW2SS,HT  
☐ PC60B31F x 1-1/4"FB,KW2SS  
☐ PC60B32F x 1-1/4"FB,KW2SS  
☐ PC60B33F x 1-1/4"FB,KW2SS  
☐ PC60B34F x 1-1/4"FB,KW2SS  
☐ PC60B35F x 1-1/4"FB,KW2SS  
☐ PC60B36F x 1-1/4"FB,KW2SS  
☐ PC60B37F x 1-1/4"FB,KW2SS  
☐ PC60B38F x 1-1/4"FB,KW2SS  
☐ PC60B39F x 1-1/4"FB,KW2SS  
☐ PC60B40F x 1-1/4"FB,KW2SS  
☐ PC60B42F x 1-1/4"FB,KW2SS  
☐ PC60B45F x 1-1/4"FB,KW2SS  
☐ PC60B46F x 1-1/4"FB,KW2SS  
☐ PC60B48F x 1-1/4"FB,KW2SS  
☐ PC60B52F x 1-1/4"FB,KW2SS  
☐ PC60B60F x 1-1/4"FB,KW2SS  
☐ PC60B12HF x 1-7/16"FB,KW2SS,HT  
☐ PC60B13HF x 1-7/16"FB,KW2SS,HT  
☐ PC60B14HF x 1-7/16"FB,KW2SS,HT  
☐ PC60B15HF x 1-7/16"FB,KW2SS,HT  
☐ PC60B16HF x 1-7/16"FB,KW2SS,HT  
☐ PC60B17HF x 1-7/16"FB,KW2SS,HT  
☐ PC60B18HF x 1-7/16"FB,KW2SS,HT  
☐ PC60B19HF x 1-7/16"FB,KW2SS,HT  
☐ PC60B20HF x 1-7/16"FB,KW2SS,HT  
☐ PC60B21HF x 1-7/16"FB,KW2SS,HT  
☐ PC60B22HF x 1-7/16"FB,KW2SS,HT  
☐ PC60B23HF x 1-7/16"FB,KW2SS,HT  
☐ PC60B24HF x 1-7/16"FB,KW2SS,HT  
☐ PC60B25HF x 1-7/16"FB,KW2SS,HT  
☐ PC60B26HF x 1-7/16"FB,KW2SS,HT  
☐ PC60B27HF x 1-7/16"FB,KW2SS,HT  
☐ PC60B28HF x 1-7/16"FB,KW2SS,HT  
☐ PC60B29HF x 1-7/16"FB,KW2SS,HT  
☐ PC60B30HF x 1-7/16"FB,KW2SS,HT  
☐ PC60B40F x 1-7/16"FB,KW2SS  
☐ PC60B42F x 1-7/16"FB,KW2SS  
☐ PC60B45F x 1-7/16"FB,KW2SS  
☐ PC60B46F x 1-7/16"FB,KW2SS  
☐ PC60B48F x 1-7/16"FB,KW2SS  
☐ PC60B52F x 1-7/16"FB,KW2SS  
☐ PC60B60F x 1-7/16"FB,KW2SS  
☐ PC60B13HF x 1-1/2"FB,KW2SS,HT  
☐ PC60B14HF x 1-1/2"FB,KW2SS,HT  
☐ PC60B15HF x 1-1/2"FB,KW2SS,HT  
☐ PC60B16HF x 1-1/2"FB,KW2SS,HT  
☐ PC60B17HF x 1-1/2"FB,KW2SS,HT  
☐ PC60B18HF x 1-1/2"FB,KW2SS,HT  
☐ PC60B19HF x 1-1/2"FB,KW2SS,HT  
☐ PC60B20HF x 1-1/2"FB,KW2SS,HT  
☐ PC60B21HF x 1-1/2"FB,KW2SS,HT

## PEER Chain Sprockets

☐ PC60B22HF x 1-1/2"FB,KW2SS,HT  
☐ PC60B23HF x 1-1/2"FB,KW2SS,HT  
☐ PC60B24HF x 1-1/2"FB,KW2SS,HT  
☐ PC60B25HF x 1-1/2"FB,KW2SS,HT  
☐ PC60B26HF x 1-1/2"FB,KW2SS,HT  
☐ PC60B27HF x 1-1/2"FB,KW2SS,HT  
☐ PC60B28HF x 1-1/2"FB,KW2SS,HT  
☐ PC60B40F x 1-1/2"FB,KW2SS  
☐ PC60B42F x 1-1/2"FB,KW2SS  
☐ PC60B45F x 1-1/2"FB,KW2SS  
☐ PC60B46F x 1-1/2"FB,KW2SS  
☐ PC60B48F x 1-1/2"FB,KW2SS  
☐ PC60B52F x 1-1/2"FB,KW2SS  
☐ PC60B60F x 1-1/2"FB,KW2SS  
☐ PC60B16HF x 1-15/16"FB,KW2SS,HT  
☐ PC60B17HF x 1-15/16"FB,KW2SS,HT  
☐ PC60B18HF x 1-15/16"FB,KW2SS,HT  
☐ PC60B19HF x 1-15/16"FB,KW2SS,HT  
☐ PC60B20HF x 1-15/16"FB,KW2SS,HT  
☐ PC60B21HF x 1-15/16"FB,KW2SS,HT  
☐ PC60B22HF x 1-15/16"FB,KW2SS,HT  
☐ PC60B40F x 1-15/16"FB,KW2SS  
☐ PC60B42F x 1-15/16"FB,KW2SS  
☐ PC60B45F x 1-15/16"FB,KW2SS  
☐ PC60B46F x 1-15/16"FB,KW2SS  
☐ PC60B48F x 1-15/16"FB,KW2SS

## #80 B-Hub Finished Bore Sprockets

☐ PC80B09HF x 1"FB,KW2SS,HT  
☐ PC80B10HF x 1"FB,KW2SS,HT  
☐ PC80B11HF x 1"FB,KW2SS,HT  
☐ PC80B12HF x 1"FB,KW2SS,HT  
☐ PC80B13HF x 1"FB,KW2SS,HT  
☐ PC80B14HF x 1"FB,KW2SS,HT  
☐ PC80B15HF x 1"FB,KW2SS,HT  
☐ PC80B16HF x 1"FB,KW2SS,HT  
☐ PC80B17HF x 1"FB,KW2SS,HT  
☐ PC80B18HF x 1"FB,KW2SS,HT  
☐ PC80B09HF x 1-1/8"FB,KW2SS,HT  
☐ PC80B10HF x 1-1/8"FB,KW2SS,HT  
☐ PC80B11HF x 1-1/8"FB,KW2SS,HT  
☐ PC80B12HF x 1-1/8"FB,KW2SS,HT  
☐ PC80B13HF x 1-1/8"FB,KW2SS,HT  
☐ PC80B14HF x 1-1/8"FB,KW2SS,HT  
☐ PC80B15HF x 1-1/8"FB,KW2SS,HT  
☐ PC80B09HF x 1-3/16"FB,KW2SS,HT  
☐ PC80B10HF x 1-3/16"FB,KW2SS,HT  
☐ PC80B11HF x 1-3/16"FB,KW2SS,HT  
☐ PC80B12HF x 1-3/16"FB,KW2SS,HT  
☐ PC80B13HF x 1-3/16"FB,KW2SS,HT  
☐ PC80B14HF x 1-3/16"FB,KW2SS,HT  
☐ PC80B15HF x 1-3/16"FB,KW2SS,HT  
☐ PC80B16HF x 1-3/16"FB,KW2SS,HT  
☐ PC80B17HF x 1-3/16"FB,KW2SS,HT

## PEER Chain Sprockets

|                                                         |                                                          |                                                          |
|---------------------------------------------------------|----------------------------------------------------------|----------------------------------------------------------|
| <input type="checkbox"/> PC80B18HF x 1-3/16"FB,KW2SS,HT | <input type="checkbox"/> PC80B11HF x 1-1/2"FB,KW2SS,HT   | <input type="checkbox"/> PC80B19HF x 1-15/16"FB,KW2SS,HT |
| <input type="checkbox"/> PC80B19HF x 1-3/16"FB,KW2SS,HT | <input type="checkbox"/> PC80B12HF x 1-1/2"FB,KW2SS,HT   | <input type="checkbox"/> PC80B20HF x 1-15/16"FB,KW2SS,HT |
| <input type="checkbox"/> PC80B20HF x 1-3/16"FB,KW2SS,HT | <input type="checkbox"/> PC80B13HF x 1-1/2"FB,KW2SS,HT   | <input type="checkbox"/> PC80B21HF x 1-15/16"FB,KW2SS,HT |
| <input type="checkbox"/> PC80B21HF x 1-3/16"FB,KW2SS,HT | <input type="checkbox"/> PC80B14HF x 1-1/2"FB,KW2SS,HT   | <input type="checkbox"/> PC80B22HF x 1-15/16"FB,KW2SS,HT |
| <input type="checkbox"/> PC80B22HF x 1-3/16"FB,KW2SS,HT | <input type="checkbox"/> PC80B15HF x 1-1/2"FB,KW2SS,HT   | <input type="checkbox"/> PC80B23F x 1-15/16"FB,KW2SS     |
| <input type="checkbox"/> PC80B23F x 1-3/16"FB,KW2SS     | <input type="checkbox"/> PC80B16HF x 1-1/2"FB,KW2SS,HT   | <input type="checkbox"/> PC80B24F x 1-15/16"FB,KW2SS     |
| <input type="checkbox"/> PC80B24F x 1-3/16"FB,KW2SS     | <input type="checkbox"/> PC80B17HF x 1-1/2"FB,KW2SS,HT   | <input type="checkbox"/> PC80B25F x 1-15/16"FB,KW2SS     |
| <input type="checkbox"/> PC80B09HF x 1-1/4"FB,KW2SS,HT  | <input type="checkbox"/> PC80B18HF x 1-1/2"FB,KW2SS,HT   | <input type="checkbox"/> PC80B26F x 1-15/16"FB,KW2SS     |
| <input type="checkbox"/> PC80B10HF x 1-1/4"FB,KW2SS,HT  | <input type="checkbox"/> PC80B19HF x 1-1/2"FB,KW2SS,HT   | <input type="checkbox"/> PC80B27F x 1-15/16"FB,KW2SS     |
| <input type="checkbox"/> PC80B11HF x 1-1/4"FB,KW2SS,HT  | <input type="checkbox"/> PC80B20HF x 1-1/2"FB,KW2SS,HT   | <input type="checkbox"/> PC80B28F x 1-15/16"FB,KW2SS     |
| <input type="checkbox"/> PC80B12HF x 1-1/4"FB,KW2SS,HT  | <input type="checkbox"/> PC80B21HF x 1-1/2"FB,KW2SS,HT   | <input type="checkbox"/> PC80B29F x 1-15/16"FB,KW2SS     |
| <input type="checkbox"/> PC80B13HF x 1-1/4"FB,KW2SS,HT  | <input type="checkbox"/> PC80B22HF x 1-1/2"FB,KW2SS,HT   | <input type="checkbox"/> PC80B30F x 1-15/16"FB,KW2SS     |
| <input type="checkbox"/> PC80B14HF x 1-1/4"FB,KW2SS,HT  | <input type="checkbox"/> PC80B40F x 1-1/2"FB,KW2SS       | <input type="checkbox"/> PC80B36F x 1-15/16"FB,KW2SS     |
| <input type="checkbox"/> PC80B15HF x 1-1/4"FB,KW2SS,HT  | <input type="checkbox"/> PC80B42F x 1-1/2"FB,KW2SS       | <input type="checkbox"/> PC80B40F x 1-15/16"FB,KW2SS     |
| <input type="checkbox"/> PC80B16HF x 1-1/4"FB,KW2SS,HT  | <input type="checkbox"/> PC80B45F x 1-1/2"FB,KW2SS       | <input type="checkbox"/> PC80B42F x 1-15/16"FB,KW2SS     |
| <input type="checkbox"/> PC80B17HF x 1-1/4"FB,KW2SS,HT  | <input type="checkbox"/> PC80B48F x 1-1/2"FB,KW2SS       | <input type="checkbox"/> PC80B45F x 1-15/16"FB,KW2SS     |
| <input type="checkbox"/> PC80B18HF x 1-1/4"FB,KW2SS,HT  | <input type="checkbox"/> PC80B54F x 1-1/2"FB,KW2SS       | <input type="checkbox"/> PC80B48F x 1-15/16"FB,KW2SS     |
| <input type="checkbox"/> PC80B19HF x 1-1/4"FB,KW2SS,HT  | <input type="checkbox"/> PC80B60F x 1-1/2"FB,KW2SS       | <input type="checkbox"/> PC80B54F x 1-15/16"FB,KW2SS     |
| <input type="checkbox"/> PC80B20HF x 1-1/4"FB,KW2SS,HT  | <input type="checkbox"/> PC80B12HF x 1-5/8"FB,KW2SS,HT   | <input type="checkbox"/> PC80B60F x 1-15/16"FB,KW2SS     |
| <input type="checkbox"/> PC80B21HF x 1-1/4"FB,KW2SS,HT  | <input type="checkbox"/> PC80B13HF x 1-5/8"FB,KW2SS,HT   | <input type="checkbox"/> PC80B13HF x 2"FB,KW2SS,HT       |
| <input type="checkbox"/> PC80B22HF x 1-1/4"FB,KW2SS,HT  | <input type="checkbox"/> PC80B14HF x 1-5/8"FB,KW2SS,HT   | <input type="checkbox"/> PC80B14HF x 2"FB,KW2SS,HT       |
| <input type="checkbox"/> PC80B23F x 1-1/4"FB,KW2SS      | <input type="checkbox"/> PC80B15HF x 1-5/8"FB,KW2SS,HT   | <input type="checkbox"/> PC80B15HF x 2"FB,KW2SS,HT       |
| <input type="checkbox"/> PC80B24F x 1-1/4"FB,KW2SS      | <input type="checkbox"/> PC80B16HF x 1-5/8"FB,KW2SS,HT   | <input type="checkbox"/> PC80B16HF x 2"FB,KW2SS,HT       |
| <input type="checkbox"/> PC80B25F x 1-1/4"FB,KW2SS      | <input type="checkbox"/> PC80B17HF x 1-5/8"FB,KW2SS,HT   | <input type="checkbox"/> PC80B17HF x 2"FB,KW2SS,HT       |
| <input type="checkbox"/> PC80B26F x 1-1/4"FB,KW2SS      | <input type="checkbox"/> PC80B18HF x 1-5/8"FB,KW2SS,HT   | <input type="checkbox"/> PC80B18HF x 2"FB,KW2SS,HT       |
| <input type="checkbox"/> PC80B27F x 1-1/4"FB,KW2SS      | <input type="checkbox"/> PC80B19HF x 1-5/8"FB,KW2SS,HT   | <input type="checkbox"/> PC80B19HF x 2"FB,KW2SS,HT       |
| <input type="checkbox"/> PC80B28F x 1-1/4"FB,KW2SS      | <input type="checkbox"/> PC80B20HF x 1-5/8"FB,KW2SS,HT   | <input type="checkbox"/> PC80B20HF x 2"FB,KW2SS,HT       |
| <input type="checkbox"/> PC80B36F x 1-1/4"FB,KW2SS      | <input type="checkbox"/> PC80B12HF x 1-3/4"FB,KW2SS,HT   | <input type="checkbox"/> PC80B40F x 2"FB,KW2SS           |
| <input type="checkbox"/> PC80B40F x 1-1/4"FB,KW2SS      | <input type="checkbox"/> PC80B13HF x 1-3/4"FB,KW2SS,HT   | <input type="checkbox"/> PC80B42F x 2"FB,KW2SS           |
| <input type="checkbox"/> PC80B42F x 1-1/4"FB,KW2SS      | <input type="checkbox"/> PC80B14HF x 1-3/4"FB,KW2SS,HT   | <input type="checkbox"/> PC80B45F x 2"FB,KW2SS           |
| <input type="checkbox"/> PC80B45F x 1-1/4"FB,KW2SS      | <input type="checkbox"/> PC80B15HF x 1-3/4"FB,KW2SS,HT   | <input type="checkbox"/> PC80B48F x 2"FB,KW2SS           |
| <input type="checkbox"/> PC80B48F x 1-1/4"FB,KW2SS      | <input type="checkbox"/> PC80B16HF x 1-3/4"FB,KW2SS,HT   | <input type="checkbox"/> PC80B54F x 2"FB,KW2SS           |
| <input type="checkbox"/> PC80B54F x 1-1/4"FB,KW2SS      | <input type="checkbox"/> PC80B17HF x 1-3/4"FB,KW2SS,HT   | <input type="checkbox"/> PC80B60F x 2"FB,KW2SS           |
| <input type="checkbox"/> PC80B60F x 1-1/4"FB,KW2SS      | <input type="checkbox"/> PC80B18HF x 1-3/4"FB,KW2SS,HT   | <input type="checkbox"/> PC80B16HF x 2-7/16"FB,KW2SS,HT  |
| <input type="checkbox"/> PC80B11HF x 1-3/8"FB,KW2SS,HT  | <input type="checkbox"/> PC80B19HF x 1-3/4"FB,KW2SS,HT   | <input type="checkbox"/> PC80B17HF x 2-7/16"FB,KW2SS,HT  |
| <input type="checkbox"/> PC80B12HF x 1-3/8"FB,KW2SS,HT  | <input type="checkbox"/> PC80B20HF x 1-3/4"FB,KW2SS,HT   | <input type="checkbox"/> PC80B18HF x 2-7/16"FB,KW2SS,HT  |
| <input type="checkbox"/> PC80B13HF x 1-3/8"FB,KW2SS,HT  | <input type="checkbox"/> PC80B30F x 1-3/4"FB,KW2SS       | <input type="checkbox"/> PC80B19HF x 2-7/16"FB,KW2SS,HT  |
| <input type="checkbox"/> PC80B14HF x 1-3/8"FB,KW2SS,HT  | <input type="checkbox"/> PC80B36F x 1-3/4"FB,KW2SS       | <input type="checkbox"/> PC80B20HF x 2-7/16"FB,KW2SS,HT  |
| <input type="checkbox"/> PC80B15HF x 1-3/8"FB,KW2SS,HT  | <input type="checkbox"/> PC80B40F x 1-3/4"FB,KW2SS       | <input type="checkbox"/> PC80B21HF x 2-7/16"FB,KW2SS,HT  |
| <input type="checkbox"/> PC80B16HF x 1-3/8"FB,KW2SS,HT  | <input type="checkbox"/> PC80B42F x 1-3/4"FB,KW2SS       | <input type="checkbox"/> PC80B22HF x 2-7/16"FB,KW2SS,HT  |
| <input type="checkbox"/> PC80B17HF x 1-3/8"FB,KW2SS,HT  | <input type="checkbox"/> PC80B45F x 1-3/4"FB,KW2SS       | <input type="checkbox"/> PC80B23F x 2-7/16"FB,KW2SS      |
| <input type="checkbox"/> PC80B18HF x 1-3/8"FB,KW2SS,HT  | <input type="checkbox"/> PC80B48F x 1-3/4"FB,KW2SS       | <input type="checkbox"/> PC80B24F x 2-7/16"FB,KW2SS      |
| <input type="checkbox"/> PC80B11HF x 1-7/16"FB,KW2SS,HT | <input type="checkbox"/> PC80B54F x 1-3/4"FB,KW2SS       | <input type="checkbox"/> PC80B25F x 2-7/16"FB,KW2SS      |
| <input type="checkbox"/> PC80B12HF x 1-7/16"FB,KW2SS,HT | <input type="checkbox"/> PC80B60F x 1-3/4"FB,KW2SS       | <input type="checkbox"/> PC80B26F x 2-7/16"FB,KW2SS      |
| <input type="checkbox"/> PC80B13HF x 1-7/16"FB,KW2SS,HT | <input type="checkbox"/> PC80B12HF x 1-7/8"FB,KW2SS,HT   | <input type="checkbox"/> PC80B27F x 2-7/16"FB,KW2SS      |
| <input type="checkbox"/> PC80B14HF x 1-7/16"FB,KW2SS,HT | <input type="checkbox"/> PC80B13HF x 1-7/8"FB,KW2SS,HT   | <input type="checkbox"/> PC80B28F x 2-7/16"FB,KW2SS      |
| <input type="checkbox"/> PC80B15HF x 1-7/16"FB,KW2SS,HT | <input type="checkbox"/> PC80B14HF x 1-7/8"FB,KW2SS,HT   | <input type="checkbox"/> PC80B29F x 2-7/16"FB,KW2SS      |
| <input type="checkbox"/> PC80B16HF x 1-7/16"FB,KW2SS,HT | <input type="checkbox"/> PC80B15HF x 1-7/8"FB,KW2SS,HT   | <input type="checkbox"/> PC80B30F x 2-7/16"FB,KW2SS      |
| <input type="checkbox"/> PC80B17HF x 1-7/16"FB,KW2SS,HT | <input type="checkbox"/> PC80B13HF x 1-15/16"FB,KW2SS,HT | <input type="checkbox"/> PC80B36F x 2-7/16"FB,KW2SS      |
| <input type="checkbox"/> PC80B18HF x 1-7/16"FB,KW2SS,HT | <input type="checkbox"/> PC80B14HF x 1-15/16"FB,KW2SS,HT | <input type="checkbox"/> PC80B40F x 2-7/16"FB,KW2SS      |
| <input type="checkbox"/> PC80B19HF x 1-7/16"FB,KW2SS,HT | <input type="checkbox"/> PC80B15HF x 1-15/16"FB,KW2SS,HT | <input type="checkbox"/> PC80B42F x 2-7/16"FB,KW2SS      |
| <input type="checkbox"/> PC80B20HF x 1-7/16"FB,KW2SS,HT | <input type="checkbox"/> PC80B16HF x 1-15/16"FB,KW2SS,HT | <input type="checkbox"/> PC80B45F x 2-7/16"FB,KW2SS      |
| <input type="checkbox"/> PC80B21HF x 1-7/16"FB,KW2SS,HT | <input type="checkbox"/> PC80B17HF x 1-15/16"FB,KW2SS,HT | <input type="checkbox"/> PC80B48F x 2-7/16"FB,KW2SS      |
| <input type="checkbox"/> PC80B22HF x 1-7/16"FB,KW2SS,HT | <input type="checkbox"/> PC80B18HF x 1-15/16"FB,KW2SS,HT | <input type="checkbox"/> PC80B54F x 2-7/16"FB,KW2SS      |
| <input type="checkbox"/> PC80B10HF x 1-1/2"FB,KW2SS,HT  |                                                          | <input type="checkbox"/> PC80B60F x 2-7/16"FB,KW2SS      |